03560.003025

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: James Phan

Group Art Unit: 2872

re Patent of: SUSUMU YASUDA, et al.

Appl. No.: 10/073,304

Filed: February 13, 2002

For: TILTABLE-BODY APPARATUS, AND METHOD OF FABRICATING THE SAME

U.S. Patent No.: 6,831,765

Issued: December 14, 2004 November 30, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Certificate DEC 0 6 2005

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

12/02/2005 HDEMESS1 00000027 6831765

01 FC:1811

100.00 OP

DEC

Patentees' undersigned attorney may be reached in our Costa Mesa,

California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Edward A. Kmett
Attorney for Patentees
Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA_MAIN 104846v1

Form #33

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,831,765

DATED

December 14, 2004

INVENTOR(S) :

SUSUMU YASUDA, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 53, "occurs" should read --occur--.

COLUMN 7:

Line 1, "across-sectional" should read --a cross-sectional--.

Line 25, "across-sectional" should read --a cross-sectional--.

Line 51, "across-sectional" should read --a cross-sectional--.

COLUMN 9:

Line 45, "SiO₂" should read --SiO₂--.

Line 55, "W," should read -- W₂--.

COLUMN 10:

Line 67, "is" should read -- are--.

COLUMN 11:

Line 50, "up-side-down" should read --upside down--.

COLUMN 13:

Line 40, "occurs" should read --occur--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,831,765</u>

No. of add'l. copies @ 30¢ per page

\$3000 P

6 2005

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,831,765

DATED

December 14, 2004

INVENTOR(S) :

SUSUMU YASUDA, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 66, "629;" should read --629,--.

COLUMN 17:

Line 50, "up-side-down" should read --upside down--.

Line 59, "there is" should read --there are--.

COLUMN 18:

Line 59, "a acceleration" should read -- an acceleration--.

COLUMN 20:

Line 38, "occurs" should read --occur--.

COLUMN 21:

Line 34, "p:" should be deleted.

COLUMN 25:

Line 4, "occurs" should read --occur--.

COLUMN 30:

Line 25, "said" should read --said each--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,831,765</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

6,831,765

DATED

December 14, 2004

INVENTOR(S) :

SUSUMU YASUDA, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 53, "occurs" should read --occur--.

COLUMN 7:

Line 1, "across-sectional" should read --a cross-sectional--.

Line 25, "across-sectional" should read --a cross-sectional--.

Line 51, "across-sectional" should read --a cross-sectional--.

COLUMN 9:

Line 45, "Si0₂" should read --SiO₂--.

Line 55, "W," should read --W₂--.

COLUMN 10:

Line 67, "is" should read -- are--.

COLUMN 11:

Line 50, "up-side-down" should read --upside down--.

COLUMN 13:

Line 40, "occurs" should read --occur--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,831,765</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

6,831,765

DATED

December 14, 2004

INVENTOR(S) :

SUSUMU YASUDA, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15:

Line 66, "629;" should read --629,--.

COLUMN 17:

Line 50, "up-side-down" should read --upside down--.

Line 59, "there is" should read --there are--.

COLUMN 18:

Line 59, "a acceleration" should read -- an acceleration--.

COLUMN 20:

Line 38, "occurs" should read --occur--.

COLUMN 21:

Line 34, "p:" should be deleted.

COLUMN 25:

Line 4, "occurs" should read --occur--.

COLUMN 30:

Line 25, "said" should read --said each--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,831,765</u>

No. of add'l. copies @ 30¢ per page

6 2005

DEC